
PARTS LIST						1 🗐 7_0	6
Name	Part	Qty	Name	part	Qty		G J
A Castor	8	5	H back frame		1	take out two screws on part "G".	H D K
B base		1	 finishing cover		1	O—F	according to the picture, use screws to connect mechanism and back frame.
C gas lift		1	J screw M8x30mm		12	insert"H"part into "G"then assemble two screws back and tweak tightly.	G D E
D sest and mechanism		1	K shim 8x22x1.5mm		12	connect"F"and"G"according to the picture.	Loose out two wheels from the steel sheets, then insert "E" under the steel sheets, tighten the wheel.
E arm rest		2	L spanner 5mm		1	4 G	Loose out the screws at the two side of "N"
F back		1	M spanner 4mm O spanner		1	put"K"under"J",insert both of them into holes and tweak tightly	9 N N N N N N N N N N N N N N N N N N N
G main lumbar frame		1	3mm N head rest		1	put"I"part upon"G"part,press until tight	Put"N"to"F"at the right position then tighten the two screws.



finish whole chair as this picture.
 adjust the handle in mechanism base on your weight.

item no.:W-80

